



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.:	<b>US/UL/QAR14.0015/08</b>	Page 1 of 1
QAR Free Ref. No.:	<b>4791648357</b>	Status: <b>Issued</b>
Details of change:	Reassessment Audit	Date of issue: <b>2025-03-26</b>
Location(s) audited:	<b>Pulsafeeder Inc.</b> 2883 Brighton Henrietta Town Line Rd Rochester, NY 14623 <b>United States of America</b>	Valid until: <b>2028-04-24</b>  Audit date: <b>2025-02-06</b>
Issuing ExCB:	<b>UL - UL Solutions (US)</b>	
Manufacturer:	<b>Pulsafeeder Inc.</b> 2883 Brighton Henrietta Town Line Road Rochester, NY 14623	
Location of Manufacturer:	<b>United States of America</b>	
Product information:	Pump Controllers and Pressure Switches	
Type of protection:	<b>Flameproof "d" Non-Electrical "h" Dust Ignition Protection by Enclosure "t"</b>	
Related QARs:	<div>US/UL/QAR14.0015/00      US/UL/QAR14.0015/01      US/UL/QAR14.0015/02 US/UL/QAR14.0015/03      US/UL/QAR14.0015/04      US/UL/QAR14.0015/05 US/UL/QAR14.0015/06      US/UL/QAR14.0015/07</div>	
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:	<div>IECEX ETL 18.0040X issue: 0      IECEX ETL 18.0040X issue: 1      IECEX ETL 18.0040X issue: 2 IECEX ETL 20.0057X issue: 0      IECEX ETL 20.0057X issue: 1      IECEX ETL 20.0057X issue: 2 IECEX UL 14.0055X issue: 0      IECEX UL 14.0118X issue: 0      IECEX UL 14.0118X issue: 1 IECEX UL 14.0118X issue: 2      IECEX UL 14.0118X issue: 3      IECEX UL 14.0118X issue: 4 IECEX UL 14.0118X issue: 5      IECEX UL 14.0118X issue: 6</div>	
Comments:		