



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **US/UL/QAR14.0015/06** Page 1 of 1
QAR Free Ref. No.: **4790290562** Status: **Issued**
Details of change: **Reassessment Audit** Date of issue: **2022-04-06**
Site(s) audited: **Pulsafeeder Inc.** Valid until: **2025-04-24**
2883 Brighton Henrietta Town Line Rd
Rochester, NY 14623
United States of America Audit date: **2022-03-11**

Issuing ExCB: **UL - UL LLC**

Manufacturer: **Pulsafeeder Inc.**
2883 Brighton Henrietta Town Line Road
Rochester, NY 14623

Location of
Manufacturer: **United States of America**

Product information: **Pump Controllers and Pressure Switches**

Protection concept: **Flameproof "d" Non-Electrical "h" Dust Ignition Protection by Enclosure "t"**

Related QARs:

[US/UL/QAR14.0015/00](#)
[US/UL/QAR14.0015/03](#)

[US/UL/QAR14.0015/01](#)
[US/UL/QAR14.0015/04](#)

[US/UL/QAR14.0015/02](#)
[US/UL/QAR14.0015/05](#)

Related Certificates (manual insertion):

Related Certificates (automatic linking):

Related Certificates for
previous versions:

IECEX ETL 18.0040X issue: 0
IECEX ETL 20.0057X issue: 0
IECEX UL 14.0118X issue: 0
IECEX UL 14.0118X issue: 3

IECEX ETL 18.0040X issue: 1
IECEX ETL 20.0057X issue: 1
IECEX UL 14.0118X issue: 1
IECEX UL 14.0118X issue: 4

IECEX ETL 18.0040X issue: 2
IECEX UL 14.0055X issue: 0
IECEX UL 14.0118X issue: 2
IECEX UL 14.0118X issue: 5

Comments: